

ALL ROUNDER Heated Jacket Size Chart



KP1308, KP1309, KP1310, KP1311
Measurements in cm.

	M	L	XL	XXL
A. Length	76	78	80	82
B. Chest	128	132	136	140
C. Hem	122	126	130	134
D. Shoulder	53	55	57	59
E. Length of Sleeve	65	66	67	68
F. Width of Sleeve	26	27	28	29
G. Collar	64	64	66	66
H. Hood Height	34	34	35	35
I. Hood Width	27	27	28	28