

Product Safety Recall

Product Information

Product Part Number and Description

K12061 Kincrome **1800kg Trolley Jack**

Batch #: AIMC36837, AIMC33966, AIMC22420, AIMC48035

Defect:

The jack failed to meet the serviceability requirements of section 5.4a, 5.5, 6.4, 6.7a and 6.7x

Effected Products:

K12061 batch #'s: AIMC36837, AIMC33966, AIMC22420, AIMC48035;
supplied from April 2013

What Should Consumers do;

Consumer Actions:

Stop using your jack immediately and return to the place of purchase, for an exchange or full refund.

Further Information:

Supplier Information:

Kincrome Tools & Equipment
3 Lakeview Drive
Scoresby VIC 3179
Ph: (03) 97307100

Supplier Web Site:

www.kincrome.com.au

Supplier Contact:

Jason Rae



See www.recalls.gov.au for
Australian Product Recall Information